

	Type	Hits	Search Text	DBs
1	BRS	10723	torque near3 convert\$4	USPAT
2	BRS	2595	(torque near3 convert\$4) and (crankshaft starter)	USPAT
3	BRS	546968	"3" and (fastener bolt screw)	USPAT
4	BRS	387	((torque near3 convert\$4) and (crankshaft starter)) and (fastener bolt screw)	USPAT
5	BRS	265	((((torque near3 convert\$4) and (crankshaft starter)) and (fastener bolt screw)) and spring	USPAT
6	BRS	122	((((torque near3 convert\$4) and (crankshaft starter)) and (fastener bolt screw)) not (((torque near3 convert\$4) and (crankshaft starter)) and (fastener bolt screw)) and spring)	USPAT
7	BRS	5808	torque near3 convert\$4	DERWENT
8	BRS	260	(torque near3 convert\$4) and (crankshaft starter)	DERWENT
9	BRS	18	((torque near3 convert\$4) and (crankshaft starter)) and (fastener bolt screw)	DERWENT

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	11714	torque near3 convert\$4	USPA T; EPO	2003/09/0 4 15:59	
2	BRS	L2	991	torque near3 convert\$4	EPO	2003/09/0 4 15:20	
3	BRS	L3	55	2 and (crankshaft starter)	EPO	2003/09/0 4 15:59	
4	BRS	L4	4270	torque near3 convert\$4	JPO	2003/09/0 4 15:59	
5	BRS	L5	0	4 and (crankshaft starter)	EPO	2003/09/0 4 15:59	
6	BRS	L6	156	4 and (crankshaft starter)	JPO	2003/09/0 4 15:59	
7	BRS	L7	15	6 and (fastener bolt screw)	JPO	2003/09/0 4 16:02	